

August 17, 2006

Revised Final Agenda
Environmental Management Advisory Board to Hanford Site

By

James A. Ajello, C. Stephen Allred, Lorraine Anderson, A.J. Barnes, Allan V. Burman, Tony Carter, George B. Estes, Dennis Ferrigno, Kenneth Hunter, Albert Joseph Kliman, Theresa Lamb, Peter Marshall, Jennifer Palazzolo, Jennifer Salisbury, David Swindle, Rebecca Wallace, Thomas Winston, Paul Dabbar, Melissa Nielson, Claudia Gleicher, Megan Barnett

August 22, 2006

REMINDER: FOR THE WTP TOUR, LEATHER BOOTS ARE REQUIRED. THE BOOTS MUST BE AT LEAST ANKLE-HIGH WITH A SUBSTANTIAL SOLE AND FLAT HEEL. NO DRESS BOOTS ARE ALLOWED. YOU MUST ALSO HAVE AT LEAST 4" SLEEVES ON YOUR SHIRTS, AND LONG PANTS.

<u>Tuesday, August 22</u>		<u>DOE</u>	<u>Other</u>
7:45 a.m.	Meet in lobby of Courtyard by Marriott. (Board A&A Motor Coach bus)	Olds	Gamache Braswell
8:00 a.m.	Travel to Fed Building for badging	same	
8:15 a.m.	Arrive back ramp at Fed Building for badging.	same	
8:45 a.m.	Travel to Cold Test Facility	same + Wiegman	
9:00 a.m.	Arrive at the Cold Test Facility for a briefing and tour. In addition, watch video on retrieval technology and Bulk Vitrification.	same	Same + Raymond
10:00 a.m.	Travel to Waste Treatment Plant. En-route discussions to include: Hanford Cleanup Overview and Tank Waste Cleanup by Steve Wiegman.	same	Same - Raymond

10:30 a.m.	Arrive at the Waste Treatment Plant for briefing and tour. <i>(snacks available)</i>	same + Furlong Harkins	
1:00 p.m.	Travel to K-Basins via 200W area.	Same – Furlong Harkins	
1:30 p.m.	Arrive at K-Basin conf room MO401/17/100K for lunch. Box Lunch: cost \$10.00		
2:00 p.m.	Begin K-Basin briefing and tour.	Klein Lutz Brockman	Gamache Braswell
4:00 p.m.	Travel back to hotel En-route discussions to include drive bys: Energy Northwest, 300 Area, FFTF / 400 Area	same	
4:45 p.m.	End of visit.		

#